

HAZARDOUS MATERIALS INCIDENT

REPORTING INFORMATION FORM

1. _____

DATE: 1-19-2014
NAME: TH Trucking

TIME: 2:37 P.M.
PHONE: 701-212-3766

AGENCY: Davison EM

2. _____

TYPE OF INCIDENT: 1437 on 19 JAN 2014 Davison County Emergency Manager Bathke received a call from Jerry at the Mitchell Police Department Dispatch. Jerry stated there was an east bound semi at mile marker 328 leaking fuel, with approximately 5 gallons spilled. Mitchell Fire Department, Davison County Sheriff and the SD Highway Patrol were on scene. EM Bathke informed Dispatch to call if the spill exceeded the 25 gallon minimum. At 1507 Jerry called back and said the spill had exceeded 25 gallons. EM Bathke arrived on scene at 1515, and noticed a large amount of fuel soaked into the soil. The soil was recently seeded and covered with straw, so it had very little vegetation; if any. The MFD had put pillows under the passenger side fuel tank to absorb some of the fuel and contain the fuel due to strong winds. The pillows from the MFD were bagged and left at the scene for recovery. They estimated 50-60 gallons of fuel spilled on the soil. See size below.

The driver informed the MFD he hit an object on the road near Chamberlain, which may have caused the puncture in the fuel tank. The Duty Officer was notified that a report would be sent once the information was collected.

EM Bathke met with the driver, Curtiss Burnham. His contact phone number is 701-212-3766. The Company address is TH Trucking, 130 S. Main, Tappen, ND. The vehicle license number is 46390 with a North Dakota plate. The US DOT number is 1647908.

On 20 JAN 2014 EM Bathke attempted to flag the area, but the soil was frozen and a flag was not placed. A picture was taken of the site, which is attached.

LOCATION: Eastbound I-90, Mile Marker 328

INJURIES: None

PLACARD #: NA

CONTAINER TYPE: Fuel Tank

CHEMICAL: Diesel Fuel

FORM: Liquid

AMOUNT: 50-60 gallons

SPILL SIZE: Triangle shape, 4' wide at top, 2' wide at bottom, approximately 20' in length.

MOVEMENT: Most of the spill ran down the hill of the I-90 ditch. Due to the high winds a small amount sprayed to the east of the main spill.

3. _____

ENDANGERED AREA: None. A small creek is to the west, but not close enough for the fuel to get to the water.

POPULATION AREA: Triangle shape, 4' wide at top, 2' wide at bottom, approximately 20' in length.

IMMEDIATE THREAT: HUMAN WILDLIFE WATER FISH OTHER

CURRENT OR POTENTIAL HEALTH PROBLEMS: None

4. _____

CURRENT OR POTENTIAL ENVIRONMENTAL PROBLEMS: Contaminated soil.

WATER BODIES/STREAMS INVOLVED: A small creek is to the west, but not close enough for the fuel to get to the water.

WHAT MEDIA WAS AFFECTED BY THE RELEASE: Soil

5. _____

CURRENT WEATHER CONDITIONS AT SCENE: Fair

WIND SPEED: 16, gust to 24 DIRECTION: N-NW TEMPERATURE: 26° CLIMATE: Calm

6. _____

SHIPPER/MANUFACTURER: ADDRESS: 130 S. Main, Tappen, ND

PHONE: 701-212-3766

DRIVER NAME: Curtiss Burnham

INSURANCE COMPANY/POLICY/ADDRESS/PHONE: The Insurance carrier is Progressive and the policy number is 01705900-0.

7. _____

AGENCIES ON SCENE: Davison County EM, Davison County Sherrif, Mitchell Fire Department, SD Highway Patrol (#173)

Incident Report: 1-605-773-3231 for Pierre Duty Officer

