



**DEPARTMENT of AGRICULTURE  
and NATURAL RESOURCES**

JOE FOSS BUILDING  
523 E CAPITOL AVE  
PIERRE SD 57501-3182  
danr.sd.gov

June 7, 2021

Victor Doroshin  
Energy Trucking, LLC  
545 Metro Place South  
Dublin, Ohio 43017

Re: No Further Action designation for DANR File# 2021.018: pertaining to a diesel fuel release that occurred near mile marker 324 on Interstate 90, West of Mitchell, SD.

Dear Mr. Doroshin:

The Department of Agriculture and Natural Resources (DANR) had reviewed the information provided regarding the transportation accident which occurred approximately eight miles west of Mitchell, South Dakota. According to the information available, the semi-truck lost control due to adverse weather and road conditions which resulted in the side-saddle tank being ruptured and reportedly 100-gallons of diesel being released from containment. GeoTek Engineering and Testing Services, Inc., was retained to perform remedial activities; however, petroleum impacts were not identified in the area associated with the accident. No adjacent utilities or other receptors were identified in the general area. For this reason, DANR is placing this case in the "No Further Action" category. The No Further Action designation means that soil contamination may remain at the site, however, it is unlikely to pose any risk to human health or further risk to the environment.

Please note if future problems arise as a result of the remaining contamination you may be responsible to perform further assessment and remediation. The No Further Action designation will be recorded in DANR's release database which can be found on the DANR website.

If you have questions or concerns about your site's No Further Action designation, please contact Marshall Brown of my staff at 605-773-3296. Thank you for your cooperation in protecting South Dakota's water resources.

Sincerely

Hunter Roberts  
Secretary

Cc: Mark Jennings, Davison County Emergency Management  
Emilia Durkin, Progressive Insurance, Plainsboro, NJ