

## DEPARTMENT of ENVIRONMENT and NATURAL RESOURCES

JOE FOSS BUILDING 523 EAST CAPITOL PIERRE, SOUTH DAKOTA 57501-3182

denr.sd.gov

December 15, 2016

Dale Wilson CHS Farmers Alliance PO Box 1286 Mitchell, SD 57301

Subject: Department of Environment and Natural Resources File Number – 2016.220 Pertaining to a release of liquid fertilizer into containment, Mitchell

Dear Mr. Wilson:

The Department of Environment and Natural Resources is contacting you regarding the above referenced event. This office has recorded information provided about this event on an initial spill report form (enclosed for your review). It is understood the available product has been recovered and will be used for its intended purpose. The procedures for assessment and remediation of a release such as this were developed to prevent pollution of the waters of the State. In this situation, the following steps must be taken:

- By January 13, 2017 please complete and return the enclosed <u>Incident Follow Up Report</u> form (this is a standard form so some questions will not apply to this situation, just skip those questions). Electronic options for completing the form can be found at *http://denr.sd.gov/des/gw/Spills/Incident\_Follow\_Up\_Report.aspx*
- Do not allow the release of accumulated water from within the tank containment system without this department's approval. Sample accumulated water quarterly (or when water is available) and provide results for department review.

Rick Lancaster has been assigned as the project manager of this case. Once Rick has reviewed all of the information on this case he will contact you to discuss any further actions that may be needed. If you have any questions or need additional information please contact Rick Lancaster or me at 605.773.3296. Thank you for your cooperation.

Sincerely.

Kim McIntosh Environmental Manager

Enclosures

cc Jeff Bathke, Davison County Emergency Management, Mitchell, SD Gary Perowitz, CHS Environmental, Morris, MN

## DENR Case No.: 2016.220 Dept. of Ag. Case No. R LANCASTER Recorded By: Reported: (mm/dd/vy 12 13 Time: 5:30 PM Reported By GARY EROWETZ 14S Organization Name: IN A. Reporter public local Organization: discharger state federal WEST STIF STREET Address City: MORATS County: State: Zip: Phone: 56267 320 28 3109 B. DISCHARGER WILSON Responsible Party Name FARMEAS ALLIANCE ALE Address 1286 State: County SD City ILTL Phone: 605 996 9200 Zip 730 FLEVATOR ROAD FACELETY As Above in B Street or Approx. Location C. INCIDENT LOCATION TANK FARM BEHEND OFFICES 3730 1 Т R Survey Description: Sec 50 METCHELL UES State: County: City: 0 Spill Time 0 OKHW Spill Date: (mm/dd/yy) hazardous substance material unknown Spilled in Water Units (Check 1) Quantity Spilled Material Type (Code/Name): oil othe E. Material 30 gal. FERTILIZER lb. bbl. oth LIGUED oth lb. bbl gal. lb. bbl gal. oth. AST fixed facility pipeline highway air transport Source of Spill: UST railway vessel F. Description: FIBERGLASS TANK groundwater within facility only Medium Affected: land water air G G SECONDARY CONTAINMENT WIEN Waterway Affected: operational error dumping Other transportation accident Reported Cause: H. CAUSE unknown equipment failure natural phenomenon Description: GASKET LEA Property damage > \$50,000 No. of deaths - OKE Damages: No. of injuries Response Action Taken AUATLABLE PRODUCT RECOVERED. TO J. ACTIONS Evacuation FOR INTENDED PURPOSE ISCO DOA discharger federal EPA local DENR Responding Agency: NOTI-Agencies Notified ACCUMULATED WATER WITHIN CONTAINMENT Comments TO BE TESTED FOR COMPONENTS OF FERTILIZER. L. COMMENTS TEST RESULTS TO BE PROVIDED TO FAILS OFFICE FOR REVIEW & APPROVAL PRIOR TO REZEASE

Environmental Events Database - Initial Report Form

Department of Environment and Natural Resources Ground Water Quality Program 523 East Capitol Avenue Pierre, South Dakota 57501-3182 Business Hours M thru F 8:00 – 5:00pm Normal business hours – (605) 773-3296 After business hours – (605) 773-3231