



DEPARTMENT of ENVIRONMENT
and NATURAL RESOURCES

JOE FOSS BUILDING
523 EAST CAPITOL
PIERRE, SOUTH DAKOTA 57501-3182

denr.sd.gov

Sarah Niewenhuis
Arnie's Service
1218 E 1st Avenue
Mitchell, SD 57301

January 24, 2019

Subject: Department of Environment and Natural Resources File Number – 2019.006
Pertaining to gasoline contamination at Arnie's Service, Mitchell

Dear Ms. Niewenhuis:

The Department of Environment and Natural Resources is contacting you regarding a report of gasoline contaminated soils at the Arnie's Service site. This office has recorded the information provided about this site on an initial spill report form (enclosed for your review). The procedures for assessment and cleanup at a site such as this were developed to prevent pollution of the state's water resources. It is understood the tank system and dispensers have been replaced. In this situation, the following steps must also be taken:

- Please direct your environmental consultant to: develop a work plan to further assess site contamination; and provide a current receptor survey for the site. The work plan should be prepared for the purpose of determining the extent and magnitude of soil and ground water contamination and the receptor survey will identify potential receptors at and near the property that might be threatened by contamination at the site.
- Please direct your consultant to establish contact with the department's project manager and provide copies of all work plans and reports for review and comment.
- By March 01, 2019, please complete and return the attached Written Contamination Incident Follow Up Report form (this is a standard form so some questions will not apply to this situation, just skip those questions). Electronic options for completing the form can be found at http://denr.sd.gov/des/gw/Spills/Incident_Follow_Up_Report.aspx

Kayla Fawcett has been assigned as the department's project manager of this case. Once Kayla has reviewed all of the information on this case she will contact you to discuss any further actions that may be needed. If you have any questions or need additional information, please do not hesitate to contact Kayla Fawcett or me at 605.773.3296. Thank you for your cooperation.

Sincerely,

Trish Kindt
Environmental Manager

enclosures

cc Jeff Bathke, Davison County Emergency Management, Mitchell
Jerald Zutz, GeoTek Engineering & Testing Services Inc., Sioux Falls
Alan Bakeberg, DENR PRCF Program, Pierre

Environmental Events Database - Initial Report Form

Dept. of Ag. Case No. _____ DNR Case No.: **2019, 006**

Reported: (mm/dd/yy) **01/23/19** Time: **1:40 PM** Recorded By: **R. LANCASTER**

A. REPORTER	Reported By: JOHN McVEY										
	Organization Name: DENR PRCF										
	Organization: <input type="checkbox"/> discharger <input type="checkbox"/> public <input checked="" type="checkbox"/> state <input type="checkbox"/> local <input type="checkbox"/> federal										
	Address: FOSS BLDG										
	City: PEERRE		County:			State: SD					
Zip: 57501		Phone: 605 773 3769									
B. DISCHARGER <small>(Responsible Party)</small>	Name: NIEW LLC SARA REYELTS / MIRANDA RESCHONG										
	Address: 1218 EAST 1ST AVE										
	City: MITCHELL		County:			State: SD					
	Zip: 57301		Phone: 605 933 1557								
C. INCIDENT LOCATION	As Above in B <input checked="" type="checkbox"/> Street or Approx. Location: ARMIES SERVICE										
	Survey Description: _____ Sec _____ T _____ R _____ 57301										
	City: MITCHELL		County: DAWSON			State: SD					
D. DATE	Spill Date: (mm/dd/yy)				Spill Time:						
E. MATERIAL	Material Type (Code/Name):		<input type="checkbox"/> hazardous substance <input type="checkbox"/> oil <input type="checkbox"/> other		material unknown	Quantity Spilled	Spilled in Water	Units (Check 1)			
	GASOLINE							lb.	bbl.	gal.	oth.
								lb.	bbl.	gal.	oth.
F. SOURCE	Source of Spill: <input type="checkbox"/> AST <input checked="" type="checkbox"/> UST <input type="checkbox"/> railway <input type="checkbox"/> vessel <input type="checkbox"/> fixed facility <input type="checkbox"/> pipeline <input type="checkbox"/> highway <input type="checkbox"/> air transport										
	Description: DISPENSERS										
G. MED.	Medium Affected: <input type="checkbox"/> air <input checked="" type="checkbox"/> land <input type="checkbox"/> water <input type="checkbox"/> groundwater <input type="checkbox"/> within facility only										
	Waterway Affected:										
H. CAUSE	Reported Cause: <input type="checkbox"/> transportation accident <input type="checkbox"/> equipment failure <input type="checkbox"/> operational error <input type="checkbox"/> natural phenomenon <input type="checkbox"/> dumping unknown <input type="checkbox"/> Other										
	Description: LEAKS (DISPENSERS) & OVERRILLS										
I. DAM.	Damages: <input type="checkbox"/> No. of injuries		<input type="checkbox"/> No. of deaths		<input type="checkbox"/> Property damage > \$50,000						
J. ACTIONS	Evacuation <input type="checkbox"/> Response Action Taken TANK SYSTEM REPLACED										
	TIER 1 ASSESSMENT - GEOTEK #18-D13										
K. NOTIFIED	Responding Agency: <input type="checkbox"/> DENR <input type="checkbox"/> DOA <input type="checkbox"/> discharger <input type="checkbox"/> federal <input type="checkbox"/> EPA <input type="checkbox"/> local										
	Agencies Notified:										
L. COMMENTS	Comments										
	TANK FACILITY 08-00031 / SAMPLE # D3 2 5' 29.1 PPM BENZENE 9,460 PPM TPH AS G										