



DEPARTMENT of ENVIRONMENT
and NATURAL RESOURCES

JOE FOSS BUILDING
523 EAST CAPITOL
PIERRE, SOUTH DAKOTA 57501-3182

denr.sd.gov

April 4, 2019

Ben Wipf
Wipf Excavating
652 27th Street NE
Huron, SD 57350

Subject: Department of Environment and Natural Resources (DENR) File Number 2019.046
Gasoline spill as result of line damage during tank system removal at All Star
Convenience, Mitchell

Dear Mr. Wipf:

The Department of Environment and Natural Resources is contacting you regarding the above referenced event. This office has recorded the information provided about this event on an initial spill report form (enclosed for your review). It is understood: gasoline spilled from damaged product lines during tank system removal; impacted soils were excavated; and the excavated soils disposed at the Mitchell Landfill. Please also:

- Complete and return the attached Written Contamination Incident Follow Up Report form no later than May 4, 2019. This is a standard form so some questions will not apply to this situation, just skip those questions. Electronic options for completing the form can be found at http://denr.sd.gov/des/gw/Spills/Incident_Follow_Up_Report.aspx
- Please also include a copy of the disposal receipts or weight tickets from the landfill.

Scott Bickler has been assigned as the project manager of DENR case #2019.046. Scott has scheduled a site inspection and will contact you to provide further direction, if necessary. Please contact Scott Bickler at 605.362.3500 or me at 605.773.3296 if you need additional information or assistance. Thank you for working to protect South Dakota's water resources.

Sincerely,

Trish Kindt
Environmental Manager

enclosures

cc: Jeff Bathke, Davison County Emergency Management, Mitchell
Alan Bakeberg, DENR PRCF Program, Pierre
Brett Schutte, DENR PRCF Program, Mitchell
Don Meyers, Meyers Oil Company, Mitchell

Environmental Events Database - Initial Report Form

P

2019.046

Dept. of Ag. Case No.

DENR Case No.

Reported: (mm/dd/yy) 4-4-19		Time:		Recorded By: Scott Bickler		
A. REPORTER	Reported By: Brett Schutte					
	Organization Name: DENR-RRCF					
	Organization: <input type="checkbox"/> discharger <input type="checkbox"/> public <input checked="" type="checkbox"/> state <input type="checkbox"/> local <input type="checkbox"/> federal					
	Address: 821 N Capital Ste 213					
	City: MITCHELL		County: DAVISON		State: SD	
Zip: 57301-1004		Phone: 605 995 8162				
B. DISCHARGER (Responsible Party)	Name: Ben Wipt Wipt Excavating					
	Address: 652 27th ST NE					
	City: Huron		County: Beadle		State: SD	
	Zip: 57350		Phone: 605 353 4351			
C. INCIDENT LOCATION	As Above in B Street or Approx. Location: All Star Convenience 43.695256 1510 S Burr ST -98.013657					
	Survey Description: _____ Sec _____ T _____ R 57301					
	City: MITCHELL		County: DAVISON		State: SD	
D. DATE						
Spill Date: (mm/dd/yy)			Spill Time:			
E. MATERIAL	Material Type (Code/Name):		Quantity Spilled		Spilled in Water	
	Gasoline		200-700			
	<input type="checkbox"/> hazardous substance <input type="checkbox"/> oil <input type="checkbox"/> material unknown <input type="checkbox"/> other				Units (Check 1) lb. bbl. <input checked="" type="checkbox"/> gal. oth. lb. bbl. gal. oth. lb. bbl. gal. oth.	
F. SOURCE	Source of Spill: <input type="checkbox"/> AST <input checked="" type="checkbox"/> UST <input type="checkbox"/> railway <input type="checkbox"/> vessel <input type="checkbox"/> fixed facility <input type="checkbox"/> pipeline <input type="checkbox"/> highway <input type="checkbox"/> air transport					
	Description: pipng					
G. MED.	Medium Affected: <input type="checkbox"/> air <input type="checkbox"/> land <input checked="" type="checkbox"/> water <input type="checkbox"/> groundwater <input type="checkbox"/> within facility only					
	Waterway Affected: _____					
H. CAUSE	Reported Cause: <input type="checkbox"/> transportation accident <input type="checkbox"/> equipment failure <input checked="" type="checkbox"/> operational error <input type="checkbox"/> dumping <input type="checkbox"/> natural phenomenon <input type="checkbox"/> unknown <input type="checkbox"/> Other					
	Description: _____					
I. DAMAGE	Damages: No. of injuries _____		No. of deaths _____		Property damage > \$50,000 _____	
	Evacuation Response Action Taken: impacted soils were removed remaining soils were tested					
K. NOTIFIED	Responding Agency: <input type="checkbox"/> DENR <input type="checkbox"/> DOA <input type="checkbox"/> discharger <input type="checkbox"/> federal <input type="checkbox"/> EPA <input type="checkbox"/> local					
	Agencies Notified: _____					
L. COMMENTS	Comments: Excavator broke through 3 product lines before they could be drained. USTs at this facility are being removed & not replaced.					

Department of Environment and Natural Resources
Ground Water Quality Program
523 East Capitol Avenue
Pierre, South Dakota 57501-3182

TANKS - 08-00064

Forman 96.015

TANK SYSTEM REMOVAL

Business Hours M thru F 8:00 - 5:00pm
Normal business hours - (605) 773-3296
After business hours - (605) 773-3231

DON MEYERS
MEYERS OIL COMP
1500 W 5TH AVE
MITCHELL SD
57301