



DENR
SOUTH DAKOTA

DEPARTMENT of ENVIRONMENT
and NATURAL RESOURCES

JOE FOSS BUILDING
523 EAST CAPITOL
PIERRE, SOUTH DAKOTA 57501-3182
denr.sd.gov

February 4, 2021

Victor Doroshin
Energy Trucking LLC
545 Metro Place S
Dublin, Ohio 43017

Subject: Department of Environment and Natural Resources File Number 2021.018 pertaining to transportation accident that occurred on I-90 near mile marker 324 west of Mitchell, SD.

Dear Mr. Doroshin,

The Department of Environment and Natural Resources is contacting you regarding the event noted above. The department has recorded information provided about the event on an initial spill report form (enclosed for your review). Based on the information provided, 100 gallons of diesel spilled when the truck jackknifed and punctured the saddle tank. The procedures for the assessment and cleanup of spills such as this were developed to protect surface and groundwater resources. In this situation, DENR requires the following:

- Employ the services of an environmental consultant certified in petroleum remediation in South Dakota, for the purposes of assessing the extent and impact of the release and to facilitate cleanup of the site.
- Fill and seed/revegetate the excavation area in a manner acceptable to the Department of Transportation.
- Provide disposal receipts and a narrative describing cleanup activities performed.
- Properly dispose of contaminated soil at a permitted municipal solid waste landfill.
- By March 2, 2021, please complete the attached Written Contamination Incident Follow Up Report form (this is a standard form so some questions will not apply to this situation, just skip those questions).

Baylee Hoff has been assigned as the project manager for this case. She will review cleanup work and will contact you if further remedial action is necessary. If you have any questions or need additional information, please do not hesitate to contact her at 605.773.3296. Thank you for your cooperation and assistance.

Sincerely,

Trish Kindt
Ground Water Quality Program
Phone: (605) 773-3296

cc: Mark Jenniges, Davison County EM, Mitchell, SD
Jodie Jaques, Ryder Trucking, Mitchell, SD
Emilia Durkin, Progress Claims, Plainsboro, NJ

South Dakota Spill Report Form

Dept. of Ag. Case No.

PRCF No.

 State Case No. **2021.018**

Reported: (mm/dd/yy) 01/30/21		Time: 22:26		Recorded By: BH	
A. REPORTER	Reported By: Mark Macy				
	Organization Name: OEM				
	Organization: <input type="checkbox"/> discharger <input type="checkbox"/> public <input type="checkbox"/> state <input checked="" type="checkbox"/> local <input type="checkbox"/> federal				
	Address:				
	City:		County:		State:
Zip:			Phone:		
B. DISCHARGER (Responsible Party)	Name: Victor Doroshin				
	Address: 545 Metro Place S				
	City: Dublin,		County:		State: OH
	Zip: 43017		Phone: 7402402204		
C. INCIDENT LOCATION	Street or Approx. Location: As Above in B: <input checked="" type="checkbox"/>				
	I-90 Near Mile marker 324				
	Survey Description: Just west of Mitchell in the median				
City: Mitchell		Zip:		County:	
				State: SD	
D. DATE	Spill Date: (mm/dd/yy) 01/30/21			Spill Time: 22:26	
	E. MATERIAL	Material Type (Code/Name):		Quantity Spilled	Spilled in Water
<input type="checkbox"/> hazardous substance <input type="checkbox"/> oil <input type="checkbox"/> material unknown <input type="checkbox"/> other					
Diesel		80-100		<input type="radio"/> lb. <input type="radio"/> bbl. <input checked="" type="radio"/> gal. <input type="radio"/> oth.	
				<input type="radio"/> lb. <input type="radio"/> bbl. <input type="radio"/> gal. <input type="radio"/> oth.	
		<input type="radio"/> lb. <input type="radio"/> bbl. <input type="radio"/> gal. <input type="radio"/> oth.			
F. SOURCE	Source of Spill: <input type="radio"/> AST <input type="radio"/> UST <input type="radio"/> railway <input type="radio"/> transport <input type="radio"/> fixed facility <input type="radio"/> pipeline <input type="radio"/> highway <input checked="" type="radio"/> other				
	Description: Saddle tank punctured				
	Regulated Tank: <input type="checkbox"/>				
G. MED.	Medium Affected: <input type="checkbox"/> air <input checked="" type="checkbox"/> land <input type="checkbox"/> water <input type="checkbox"/> groundwater <input type="checkbox"/> within facilities only				
	Waterway Affected:				
H. CAUSE	Reported Cause: <input checked="" type="radio"/> transportation accident <input type="radio"/> operational error <input type="radio"/> dumping <input type="radio"/> equipment failure <input type="radio"/> natural phenomenon <input type="radio"/> unknown <input type="radio"/> Other:				
	Description: Driving too fast for conditions				
I. DAM-AGES	No. of injuries:		No. of deaths:		
J. ACTIONS	Response Action Taken:				
	None				
K. NOTIFIED	Responding Agency: <input type="checkbox"/> DENR <input type="checkbox"/> DOA <input type="checkbox"/> discharger <input type="checkbox"/> federal <input type="checkbox"/> EPA <input checked="" type="checkbox"/> local				
	Agencies Notified: DENR				
L. COMMENTS	Comments:				
	Claim #21-3256942				

Department of Environment and Natural Resources
 Ground Water Quality Program
 523 East Capitol Avenue
 Pierre, South Dakota 57501

Business Hours M thru F 8:00 - 5:00 pm
 Normal business hours - (605) 773-3296
 After business hours - (605) 773-3231