

INCIDENT FOLLOW-UP REPORTRETURN
COMPLETED
FORM
TOSOUTH DAKOTA DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
GROUND WATER QUALITY PROGRAM
JOE FOSS BUILDING
523 EAST CAPITOL AVENUE
PIERRE SD 57501-3182**RECEIVED**

JUN 14 2021

**INSPECTION, COMPLIANCE
AND REMEDIATION****SPILL LOCATION** (Identify Either: Physical Address / Direction and Distance to Nearest Intersection / Direction and40509 247th Street
Mitchell, SD 57301

LATITUDE/LONGITUDE: 43.801, -90.103

SURVEY LOCATION (Township/Range/Section/Quarter): NW 1/4 Sc 234, T-404-N, R-61-W

LAND USE (Residential, Commercial, Agricultural, Industrial, Other -- describe) Commercial

RESPONSIBLE PARTY: POET Biorefining Mitchell

MAILING ADDRESS: 40509 247th Street

CITY: Mitchell

TELEPHONE NUMBER(S): (605) 996-1686

PROPERTY OWNER: POET Biorefining Mitchell

MAILING ADDRESS: 40509 247th Street

CITY: Mitchell

TELEPHONE NUMBER(S): (605) 996-1686

ENVIRONMENTAL CONSULTANT / CLEANUP CONTRACTOR: POET Biorefining Mitchell

MAILING ADDRESS 40509 247th Street

CITY: Mitchell

TELEPHONE NUMBER(S): (605) 996-1686

INSURANCE PROVIDER:

NAME OF INSURED:

POLICY NUMBER AND CLAIM NUMBER:

MAILING ADDRESS:

CITY:

TELEPHONE NUMBER(S):

FOLLOW-UP REPORT CONTINUED

DENR CASE FILE #: 2021.069 & 2021.070

(Page 2 of 2)

TYPE / NAME OF PRODUCT SPILLED: Corn Mash

TOTAL AMOUNT OF PRODUCT SPILLED: 35 GAL & 50 GAL

AMOUNT OF PRODUCT RECOVERED: 85 GAL

WAS SPILL CONTAINED TO IMMEDIATE AREA? Yes

WAS SURFACE WATER OR GROUND WATER IMPACTED BY SPILL? No

DISTANCE TO AND NAME OF NEAREST SURFACE WATER OR DRAINAGE:

N/A - +1,000 ft from nearest surface water location

DISTANCE TO NEAREST DRINKING WATER WELL: N/A

OWNER OF NEAREST DRINKING WATER WELL: N/A

IF EXCAVATED, DIMENSIONS OF EXCAVATION: 375 sqft X 1/4 inch deep & 625 sqft X 1/4 inch deep

CUBIC YARDS EXCAVATED: 0.87 cu yd & 1.45 cu yd, or 2.32 cu yd in total

WERE THE EXCAVATED SUBSTANCES STOCKPILED? (If yes, describe how and where the substances were stockpiled.)

N/A

DATE MATERIAL (EXCAVATED AND/OR RECOVERED) WAS DISPOSED: 5/25/2021

DISPOSAL SITE: (Name of Facility) Miedema Sanitation rolloff hauled to Mitchell Sanitary Landfill

IF "LAND-APPLIED" **!!REQUIRES APPROVAL!!** : (Property Owner, address, telephone; Survey Location; Latitude/Longitude; Nearest Water Body; Distance to Nearest Water Body; Number of Acres)

41176 256th Street
Mitchell, SD 57301

NARRATIVE OF OTHER ACTIONS TAKEN AND ADDITIONAL WORK PLANNED:

The spill was contained to the immediate area by using DDGs to stop the corn mash from entering any storm water drains/conveyances. All contacted dirt/gravel was taken to Wet Cake Pad 2 (concrete pad) for de-watering. After the contacted debris was determined to be dry enough, the team disposed of it in the dumpster to be taken to Mitchell Sanitary Landfill.

The debris was disposed of on 5/25/2021.

ATTACH ANALYTICAL RESULTS AND DISPOSAL RECEIPTS, IF REQUIRED

FORM COMPLETED BY: Sarah Blaine DATE: 6/8/2021