

**INCIDENT FOLLOW-UP REPORT**RETURN  
COMPLETED  
FORM  
TOSOUTH DAKOTA DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES  
GROUND WATER QUALITY PROGRAM  
JOE FOSS BUILDING  
523 EAST CAPITOL AVENUE  
PIERRE SD 57501-3182SPILL LOCATION (Identify Either: Physical Address / Direction and Distance to Nearest Intersection / Direction and  
1/2 mile west of 399th on 263rd. South side of road

LATITUDE/LONGITUDE: \_\_\_\_\_

SURVEY LOCATION (Township/Range/Section/Quarter): \_\_\_\_\_

LAND USE (Residential, Commercial, Agricultural, Industrial, Other – describe) AgriculturalRESPONSIBLE PARTY: CHS/Farmeres AllianceMAILING ADDRESS: P.O. Box 1286CITY: Mitchell TELEPHONE NUMBER(S): (605) 996-7004 \_\_\_\_\_PROPERTY OWNER: Randy BurmeisterMAILING ADDRESS: 39843 263edCITY: mt vernon TELEPHONE NUMBER(S): (605) 236-5756 \_\_\_\_\_

ENVIRONMENTAL CONSULTANT / CLEANUP CONTRACTOR: \_\_\_\_\_

MAILING ADDRESS \_\_\_\_\_

CITY: \_\_\_\_\_

TELEPHONE NUMBER(S): \_\_\_\_\_

INSURANCE PROVIDER: \_\_\_\_\_

NAME OF INSURED: \_\_\_\_\_

POLICY NUMBER AND CLAIM NUMBER: \_\_\_\_\_

MAILING ADDRESS: \_\_\_\_\_

CITY: \_\_\_\_\_

TELEPHONE NUMBER(S): \_\_\_\_\_

**FOLLOW-UP REPORT CONTINUED**

DENR CASE FILE #: \_\_\_\_\_ (Page 2 of 2)

TYPE / NAME OF PRODUCT SPILLED: Power Max, Extendamax, Providence & Govern

TOTAL AMOUNT OF PRODUCT SPILLED: 84 gallons

AMOUNT OF PRODUCT RECOVERED: 0

WAS SPILL CONTAINED TO IMMEDIATE AREA? yes

WAS SURFACE WATER OR GROUND WATER IMPACTED BY SPILL? no

DISTANCE TO AND NAME OF NEAREST SURFACE WATER OR DRAINAGE:

DISTANCE TO NEAREST DRINKING WATER WELL: \_\_\_\_\_

OWNER OF NEAREST DRINKING WATER WELL: \_\_\_\_\_

IF EXCAVATED, DIMENSIONS OF EXCAVATION: 10 ft x 15ft

CUBIC YARDS EXCAVATED: 55 yd's

WERE THE EXCAVATED SUBSTANCES STOCKPILED? (If yes, describe how and where the substances were stockpiled.)

No

DATE MATERIAL (EXCAVATED AND/OR RECOVERED) WAS DISPOSED: 6-15-2021

DISPOSAL SITE: (Name of Facility) Tri county land fill, Pukwana, SD

IF "LAND-APPLIED" **!!REQUIRES APPROVAL!!** : (Property Owner, address, telephone; Survey Location; Latitude/Longitude; Nearest Water Body; Distance to Nearest Water Body; Number of Acres)

NARRATIVE OF OTHER ACTIONS TAKEN AND ADDITIONAL WORK PLANNED:

Soil samples were taken and have been sent to a lab. Waiting on results. Site has been backfilled and fence replaced. Grass will be reseeded after givin the go ahead.

***ATTACH ANALYTICAL RESULTS AND DISPOSAL RECEIPTS, IF REQUIRED***

FORM COMPLETED BY: Dale Wilson DATE: 6-23-2021