

South Dakota Spill Report Form

PRCF #:

Case #:

Reported (MM/DD/YY):		Time:		Recorded By:			
A. REPORTER	Reported By:						
	Organization Name:			Discharger Public State Local Federal			
	Phone:			Email:			
	Address:						
	City:			State:		Zip:	
B. DISCHARGER (Responsible Party)	As Above in A						
	Name:						
	Address:						
	City:			State:		Zip:	
C. INCIDENT DATE & LOCATION	As Above in B						
	Spill Date: (MM/DD/YY)			Spill Time:			
	Street or Approx. Location:						
	Survey Description:						
	City:		County:		State:		Zip:
D. MATERIAL	Material type (Code/Name):		Hazardous Substance Material Unknown	Oil Other	Quantity Spilled	Spilled in Water	Units (Check one)
							lb. bbl. gal. oth.
							lb. bbl. gal. oth.
							lb. bbl. gal. oth.
E. SOURCE	Source of Spill: AST UST Railway Transport Fixed Facility Pipeline Highway Other						
	Description:						
	Regulated Tank Facility: Tank Facility ID #:						
F. MEDIUM	Medium Affected: Air Land Water Groundwater Within Facilities Only						
	Waterway Affected:						
G. CAUSE	Reported Cause:		Transportation Accident Natural Phenomenon	Operational Error Unknown	Dumping Other	Equipment Failure	
	Description:						
H. DAM- AGES	# of Injuries:			# of Fatalities:			
I. ACTIONS	Response Action Taken:						
K. NOTIFIED	Responding Agency: DANR Local Discharger Federal EPA Other						
	Agencies Notified:						
K. COMMENTS	Comments:						

Department of Agriculture and Natural Resources
Inspection, Compliance, and Remediation Program
523 East Capitol Avenue
Pierre, South Dakota 57501

Business Hours M – F 8:00-5:00 pm
Normal Business Hours- (605)773-3296
After Business Hours- (605) 773-3231



**DEPARTMENT of AGRICULTURE
and NATURAL RESOURCES**

JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

Caitlin Black
Project #EM263326S3-CCB207
Cura Emergency Services
6205 Chapel Hill BLVD Ste 100
Plano, TX 75093

July 10, 2026

Subject: Department of Agriculture and Natural Resources File Number #2026.098: pertaining to a petroleum release near Grassland Drive and Cabela Drive, Mitchell, South Dakota.

Dear Ms. Black,

The Department of Agriculture and Natural Resources (DANR) is contacting you regarding the event noted above. A copy of the initial spill report form is enclosed for your review. Based on the information provided, approximately 50 gallons of petroleum were released as a result of a single vehicle accident. The responsible party is LTL Service Incorporated. The procedures for the assessment and cleanup of spills such as this were developed to protect surface and groundwater resources. In this situation, DANR requires the following work be performed:

- Retain an environmental consultant certified to perform petroleum remediation in South Dakota. Direct your consultant to excavate contaminated soil and properly dispose of all contaminated materials at a permitted municipal solid waste facility;
- Backfill the excavation area with clean soil;
- Provide DANR with post-cleanup photos and landfill receipts;
- By **August 10, 2026**, please complete and return the attached Written Contamination Incident Follow Up Report form.

Hanna Kollbaum has been assigned as the project manager for this case. She will review the information provided and will contact you if further remedial action is necessary. If you have questions or need additional information, please do not hesitate to contact her at (605) 773-3296. Thank you for your cooperation and assistance.

Sincerely,

Jaclyn McGuire
Inspection, Compliance, & Remediation Program
(605) 773-3296

cc: Jeff Bathke, Davison County Emergency Manager
Karen Wegleitner, Davison County Deputy Emergency Manager
Matt Kromraj, LTL Service Incorporated
Mike Blount, Avera