

INCIDENT FOLLOW-UP REPORT

(Page 1 of 2)

DANR CASE FILE #: 2026.077

**RETURN
COMPLETED
FORM TO:**

SOUTH DAKOTA DEPARTMENT OF AGRICULTURE AND NATURAL RESOURCES (DANR)
INSPECTION, COMPLIANCE, AND REMEDIATION PROGRAM
JOE FOSS BUILDING
523 EAST CAPITOL AVENUE
PIERRE SD 57501-3182

NAME/TYPE OF PRODUCT SPILLED: Soybean Salad Oil / Vegetable Oil
TOTAL AMOUNT OF PRODUCT SPILLED: Approximately 150 gallons
POUNDS OF ACTIVE INGREDIENT SPILLED (fertilizer/pesticide spills): N/A
AMOUNT OF PRODUCT RECOVERED: All
WAS SURFACE WATER OR GROUND WATER IMPACTED BY THE SPILL?: No
SPILL DATE: May 26, 2026 DATE CLEANUP OCCURRED: May 28, 2026

SPILL LOCATION (physical address, directions, distance to nearest intersection or landmark, etc.):
41021 257th Street Mitchell, SD 57301

LATITUDE/LONGITUDE: 43.656498 / -98.004495

LAND USE (Residential, Commercial, Agricultural, Industrial, Other – describe): Industrial

RESPONSIBLE PARTY: High Plains Processing

MAILING ADDRESS: 41021 257th Street

CITY/STATE: Mitchell, SD 57301 TELEPHONE NUMBER: 605-627-9240

PROPERTY OWNER: SD Soybean Processors

MAILING ADDRESS: 100 Caspian Avenue

CITY/STATE: Volga, SD TELEPHONE NUMBER: 605-627-9240

CONSULTANT / CLEANUP CONTRACTOR (if applicable): Precision Grading

MAILING ADDRESS: 40730 247th Street

CITY/STATE: Mitchell, SD TELEPHONE NUMBER: 605-656-0016

INSURANCE PROVIDER (if applicable): N/A

NAME OF INSURED: _____

POLICY NUMBER: _____ CLAIM NUMBER: _____

MAILING ADDRESS: _____

CITY/STATE: _____ TELEPHONE NUMBER: _____

INCIDENT FOLLOW-UP REPORT (Page 2 of 2)DANR CASE FILE #: 2026.077

WAS SOIL EXCAVATED?: Minimal DIMENSIONS OF EXCAVATION: N/A
CUBIC YARDS EXCAVATED: N/A
DISPOSAL SITE (Name of Facility): Mitchell Sanitary Landfill
DISPOSAL DATE: 5-28-26

If soil was disposed, attach copies of disposal receipts

FERTILIZER/PESTICIDE SPILLS ONLY**!!REQUIRES DANR PRE-APPROVAL!!**

WILL THE CONTAMINATED SOIL/MATERIAL BE LAND APPLIED?: _____
WHAT CROP IS/WILL BE GROWN ON THE LAND APPLICATION SITE?: _____
LEGAL DESCRIPTION OF THE LAND APPLICATION SITE: _____
TOTAL ACRES SOIL/MATERIAL WILL BE APPLIED TO: _____
YARDS/POUNDS/ETC. OF SOIL/MATERIAL TO BE APPLIED: _____
CONCENTRATION OF CHEMICAL IN THE SOIL/MATERIAL TO BE APPLIED?: _____

**THIS SECTION
FOR DANR
OFFICE USE
ONLY**


LAND APPLICATION APPROVAL DATE: _____

APPLICATION APPROVED BY: _____

WAS SPILL CONTAINED TO IMMEDIATE AREA?: YesDISTANCE TO AND NAME OF NEAREST SURFACE WATER (include currently dry perennial streams): _____
1 mile south to Enemy CreekDISTANCE TO NEAREST WATER WELL (if applicable): N/AOWNER OF NEAREST WATER WELL (if applicable): N/A

DESCRIBE RESPONSE ACTION AND ADDITIONAL WORK PLANNED: _____

Spill investigation found that the primary source of the spill was from operator error not attaching the chain anchor between the loading pipe and the railcar. Operators have reviewed SOP's for retraining. All contamination and spilled product has been cleaned up and properly disposed of and replaced with new rock and material.

FORM COMPLETED BY: Jason L Converse  DATE: 6-16-2026E-MAIL ADDRESS: jason.converse@sdsbp.com